IN THE SPECIFICATION

Please amend the paragraph beginning on line 15 of page 2, as follows: In practice attempts to incorporate appropriate pigments in the glass shell of the known markers, so that the reflected light is has the correct colour, have been unsuccessful. This is primarily because there is no readily available pigment which is compatible with the glass moulding process and which will be resistant to the ultraviolet light that the marker will be subjected to in use. The use of differently coloured reflectors internally in the marker has also proved to be unsuccessful.

Please amend the paragraph beginning on line 28 of page 5 as follows: With reference to Figures 1 to 7, the shell is of generally circular shape in plan and has a raised, central rib 16 extending diametrically. The rib 30 terminates laterally at vertical shoulders 18 and longitudinally it merges into end structures 20 that extending circularly arcuately curved end structures 20. Externally planar walls 22 extend, at opposite inclinations, downwardly from the lower edges of the shoulders 18 to horizontal walls 24. The walls 24 extending horizontal walls 24 which extend outwardly to meet, at shoulders 26, the upper edge of a generally conical wall portion 28. The latter wall portion merges with a round cylindrical side wall portion 30 that extends downwardly to a peripheral, laterally projecting flange 32 of circular shape.